

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Office of Vehicle Safety Compliance
COMPLIANCE STATUS REPORT
REPORT DATE: FEBRUARY 15, 2004

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "**CI-208-020320**")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a reasonable expectation that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "**PE-214-020320**")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a possibility of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

IN (Inspection)

CP (Complaint)

MD (Manufacturer Defect)

ID (Part 574)

MI (Manufacturer Inquiry)

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R – Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive
FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

STYLE/COMPONENT - Information for motor vehicle or equipment item

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure

FAIL - I: inspection failure

FAIL - L: labeling or instruction failure

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
1	101	Controls and Displays (Inspection)	Vehicle	Insp.-1
2	102	Transmission Shift Lever Sequence, etc. (I)	Vehicle	Insp.-2
3	103	Windshield Defrosting & Defogging Systems	Vehicle-1	TEST
4	104	Windshield Wiping & Washing Systems	Vehicle-2	TEST
5	105	Hydraulic Brake System	Vehicle-3	TEST
6	106	Brake Hoses	Equip.-1	TEST
7	108	Lamps, Reflective Devices, etc.	Equip.-2	TEST
8	109	Passenger Car New Pneumatic Tires	Equip.-3	TEST
9	110	Passenger Car Tire Selection & Rims	Vehicle-4	TEST
10	111	Rearview Mirrors	Vehicle-5	TEST
11	113	Hood Latch Systems (Inspection)	Vehicle	Insp.-3
12	114	Theft Protection	Vehicle-6	TEST
13	116	Hydraulic Brake Fluids	Equip.-4	TEST
14	117	Retreaded Pneumatic Tires (Inspection)	Equipment	Insp.-4
15	118	Power Operated Window Systems	Vehicle-7	TEST
16	119	Truck/Bus New Pneumatic Tires	Equip.-5	TEST
17	120	Truck/Bus Tire Selection & Rims	Vehicle-8	TEST
18	121	Air Brake Systems	Vehicle-9	TEST
19	122	Motorcycle Brake Systems	Vehicle-10	TEST
20	123	Motorcycle Controls & Displays (Inspection)	Vehicle	Insp.-5
21	124	Accelerator Control Systems	Vehicle-11	TEST
22	125	Warning Devices	Equip.-6	TEST
23	129	Passenger Car New Non-Pneumatic Tires	Equip.-7	TEST
24	131	School Bus Pedestrian Safety Devices	Vehicle-12	TEST
25	135	Passenger Car Brake Systems	Vehicle-13	TEST
26	201	Occupant Protection in Interior Impact	Vehicle-14	TEST
27	202	Head Restraints	Vehicle-15	TEST
28	203	Impact Prot. for Driver from Strg. Control	Vehicle-16	TEST
29	204	Steering Control Rearward Displacement	Vehicle-17	TEST
30	205	Glazing Materials (Inspection)	Equipment	Insp.-6
31	206	Door Locks & Door Retention Components	Equip.-8	TEST

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
32	207	Seating Systems	Vehicle-18	TEST
33	208	Occupant Crash Protection	Vehicle-19	TEST
34	209	Seat Belt Assemblies	Equip.-9	TEST
35	210	Seat Belt Assembly Anchorages	Vehicle-20	TEST
36	212	Windshield Mounting	Vehicle-21	TEST
37	213	Child Restraint Systems	Equip.-10	TEST
38	214	Side Impact Protection	Vehicle-22	TEST
39	216	Roof Crush Resistance	Vehicle-23	TEST
40	217	Bus Window Retention & Release	Vehicle-24	TEST
41	218	Motorcycle Helmets	Equip.-11	TEST
42	219	Windshield Zone Intrusion	Vehicle-25	TEST
43	220	School Bus Rollover Protection	Vehicle-26	TEST
44	221	School Bus Body Joint Strength	Vehicle-27	TEST
45	222	School Bus Passenger Seating	Vehicle-28	TEST
46	223	Rear Impact Guards	Equip.-12	TEST
47	224	Rear Impact Protection (Inspection)	Vehicle	Insp.-7
48	225	Child Restraint Anchorage Systems	Vehicle-29	TEST
49	301	Fuel System Integrity	Vehicle-30	TEST
50	302	Flammability of Interior Materials	Equip.-13	TEST
51	303	Fuel System Integrity of CNG Vehicles	Vehicle-31	TEST
52	304	CNG Fuel Container Integrity	Equip.-14	TEST
53	305	Electric Vehicles	Vehicle-32	TEST
54	401	Interior truck Release	Vehicle	TEST
55	500	Low Speed Vehicle Requirements	Vehicle-33	TEST
SUMMARY: 34 vehicle standards, 14 equipment standards, 7 inspection standards				

REPORTS ACCEPTED DURING JANUARY 2004 FOR FY 2004 TEST PROGRAM

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO
120	TRC 002	DAIMLER/ CHRYSLER	2004 CHRYSLER PACIFICA MPV 4-DOOR	PASS 636945
135	TRC 002	DAIMLER/ CHRYSLER	2004 CHRYSLER PACIFICA MPV 4-DOOR	PASS 636923
214	TRC 012	TOYOTA	2004 LEXUS RX 330 MPV 4-DOOR	PASS 636925

REPORTS ACCEPTED DURING JANUARY 2004 FOR FY 2003 TEST PROGRAM

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO
201	VER 002	TOYOTA	2003 TOYOTA COROLLA 4-DOOR SEDAN	PASS 637012
213	MGA 001	RECARO	2003 RECARO START CHILD RESTRAINT	PASS 636924
213	MGA 002	EVENFLO	2003 EVENFLO PORTABOUT 5 CHILD RESTRAINT	PASS 636926
213	MGA 003	EVENFLO	2003 EVENFLO PORTABOUT 3 CHILD RESTRAINT	PASS 636927
213	MGA 004	EVENFLO	2003 EVENFLO CHASE CHILD RESTRAINT	PASS 636928
213	MGA 005	EVENFLO	2003 EVENFLO TRIBUTE CHILD RESTRAINT	PASS 636942
213	MGA 006	EVENFLO	2003 EVENFLO VICTORY 5 CHILD RESTRAINT	FAIL-P ¹ 636943
213	MGA 007	EVENFLO	2003 EVENFLO VANGUARD 5 CHILD RESTRAINT	FAIL-P ² 636955
213	MGA 008	EVENFLO	2003 EVENFLO TITAN CHILD RESTRAINT	PASS 636944
213	MGA 009	EVENFLO	2003 EVENFLO VANGUARD CHILD RESTRAINT	PASS 636946
213	MGA 010	EVENFLO	2003 EVENFLO TRIUMPH CHILD RESTRAINT	PASS 636947
213	MGA 011	EVENFLO	2003 EVENFLO COMET 5 CHILD RESTRAINT	PASS 636948
213	MGA 012	EVENFLO	2003 EVENFLO TITAN 5 CHILD RESTRAINT	PASS 636949

Footenote:

¹ An Evenflo Victory 5 child restraint had a performance failure to a requirement of FMVSS No. 213, Child Restraint Systems. In a sled test simulating a 30 mph frontal crash, a portion of the seat back separated which is a failure of the child restraint system integrity.

² An Evenflo Vanguard 5 child restraint had a performance failure to a requirement of FMVSS No. 213, Child Restraint Systems. In a sled test simulating a 30 mph frontal crash, the 3-year-old child dummy's head moved forward 826 mm, exceeding the 813 mm maximum allowed.

REPORTS ACCEPTED DURING JANUARY 2004 FOR FY 2003 TEST PROGRAM

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO
213	MGA 013	EVENFLO	2003 EVENFLO DISCOVERY CHILD RESTRAINT	PASS 636950
213	MGA 014	EVENFLO	2003 EVENFLO SIGHTSEER CHILD RESTRAINT	PASS 636951
213	MGA 015	EVENFLO	2003 EVENFLO TOT TAXI CHILD RESTRAINT	PASS 636952
213	MGA 016	EVENFLO	2003 EVENFLO TRIBUTE 5 CHILD RESTRAINT	PASS 636953
213	MGA 017	EVENFLO	2003 EVENFLO EXPRESS CHILD RESTRAINT	PASS 636954
213	MGA 018	EVENFLO	2003 EVENFLO RIGHT FIT CHILD RESTRAINT	PASS 636956
213	MGA 019	DOREL JUVENILE	2003 COSCO ALPHA OMEGA CHILD RESTRAINT	PASS 636939
213	MGA 020	DOREL JUVENILE	2003 COSCO TOURIVA CHILD RESTRAINT	PASS 636940
213	MGA 021	DOREL JUVENILE	2003 COSCO REGAL RIDE CHILD RESTRAINT	PASS 636941
213	MGA 022	DOREL JUVENILE	2003 DOREL AUTO BOOSTER CHILD RESTRAINT	PASS 636957
213	MGA 023	DOREL JUVENILE	2003 COSCO TOURIVA CHILD RESTRAINT	PASS 636929
213	MGA 024	DOREL JUVENILE	2003 COSCO ALPHA OMEGA CHILD RESTRAINT	PASS 636930
213	MGA 025	DOREL JUVENILE	2003 DOREL VISTA CHILD RESTRAINT	PASS 636958
213	MGA 026	DOREL JUVENILE	2003 COSCO ARRIVA CHILD RESTRAINT	PASS 636931
213	MGA 027	DOREL JUVENILE	2003 DOREL SUMMIT CHILD RESTRAINT	PASS 636959
213	MGA 028	DOREL JUVENILE	2003 DOREL COMMUTER DX CHILD RESTRAINT	PASS 636960
213	MGA 029	DOREL JUVENILE	2003 COSCO ULTRA DREAM RIDE CHILD RESTRAINT	PASS 636932
213	MGA 030	DOREL JUVENILE	2003 DOREL HIGHBACK BOOSTER CHILD RESTRAINT	PASS 636961
213	MGA 031	DOREL JUVENILE	2003 DOREL HIGHBACK BOOSTER CHILD RESTRAINT	PASS 636962
213	MGA 032	DOREL JUVENILE	2003 DOREL HIGH RISE CHILD RESTRAINT	PASS 636963
213	MGA 033	DOREL JUVENILE	2003 DOREL GRAND EXPLORER CHILD RESTRAINT	PASS 636964
213	MGA 034	DOREL JUVENILE	2003 DOREL VENTURA CHILD RESTRAINT	PASS 636965
213	MGA 035	DOREL JUVENILE	2003 COSCO ALPHA OMEGA LX CHILD RESTRAINT	PASS 636933

REPORTS ACCEPTED DURING JANUARY 2004 FOR FY 2003 TEST PROGRAM

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO
213	MGA 036	DOREL JUVENILE	2003 DOREL COMPLETE VOYAGE CHILD RESTRAINT	PASS 636966
213	MGA 037	DOREL JUVENILE	2003 DOREL COMPLETE VOYAGE CHILD RESTRAINT	PASS 636967
213	MGA 038	DOREL JUVENILE	2003 DOREL COMPLETE VOYAGE CHILD RESTRAINT	PASS 636968
213	MGA 039	DOREL JUVENILE	2003 COSCO COMFORT RIDE CHILD RESTRAINT	PASS 636934
213	MGA 040	DOREL JUVENILE	2003 DOREL HIGHBACK BOOSTER CHILD RESTRAINT	PASS 636969
213	MGA 041	DOREL JUVENILE	2003 COSCO DESIGNER 22 CHILD RESTRAINT	PASS 636935
213	MGA 042	DOREL JUVENILE	2003 DOREL VANTAGE CHILD RESTRAINT	PASS 636970
213	MGA 043	DOREL JUVENILE	2003 COSCO DESIGNER 22 CHILD RESTRAINT	PASS 636936
213	MGA 044	DOREL JUVENILE	2003 DOREL TOTE'N'GO CHILD RESTRAINT	PASS 636971
213	MGA 045	PEG-PEREGO S.P.	2003 PEG-PEREGO PRIMO VIAGGIO CHILD RESTRAINT	PASS 636937
213	MGA 046	SAFELINE	2003 SAFELINE SIT'N'STROLL CHILD RESTRAINT	FAIL-P ³ 636938
213	MGA 047	JUPITER IND.	2003 JUPITER KOMFORT KRUISER CHILD RESTRAINT	PASS 636972

FAILURE LEGEND: P - PERFORMANCE; I - INSPECTION; L – LABELING

³ A Safeline Sit'N'Stroll child restraint had a performance failure to a requirement of FMVSS No. 213, Child Restraint Systems. In a sled test simulating a 30 mph frontal crash, the 3-year-old child dummy's head moved forward 873 mm, exceeding the 813 mm maximum allowed.

TIRE REPORTS ACCEPTED JANUARY 2004 FOR FY 2003 TEST PROGRAM

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	RESULT/ HS NO.
575	UTG 197	UNIROYAL GOODRICH TIRE MFG.	2003 FISK PHANTOM A/P STEEL RADIAL ANHFF9DD2802	PASS 6276318
575	UTG 198	UNIROYAL GOODRICH TIRE MFG.	2003 FISK PHANTOM A/P STEEL RADIAL ANHFF9DD2802	PASS 6276319
575	UTG 201	MICHELIN NORTH AMERICAN (CANADA) INC.	2003 MICHELIN XW4 RADIAL B3DBBALX2802	PASS 6276320
575	UTG 202	MICHELIN NORTH AMERICAN (CANADA) INC.	2003 MICHELIN XW4 RADIAL B3DBBALX2802	PASS 6276321
575	UTG 205	YOKOHAMA TIRE CORP.	2003 YOKOHAMA GEOLANDER H/T CCBN8WC1701	PASS 6276322
575	UTG 206	YOKOHAMA TIRE CORP.	2003 YOKOHAMA GEOLANDER H/T CCBN8WC1701	PASS 6276323
575	UTG 209	OHTSU TIRE & RUBBER CO.	2003 FALKEN ZIE X ZD-502 V4KWM081602	PASS 6276324
575	UTG 210	OHTSU TIRE & RUBBER CO.	2003 FALKEN ZIE X ZD-502 215/65R15	PASS 6276325
575	UTG 213	KELLY-SPRINGFIELD TIRE CO.	2003 ULTRA TOUR LS PLM319LR2502	PASS 6276326
575	UTG 214	KELLY-SPRINGFIELD TIRE CO.	2003 ULTRA TOUR LS PLM319LR2502	PASS 6276327
575	UTG 217	MICHELIN NORTH AMERICA INC.	2003 MICHELIN PILOT XGT H4 3R3VC4YX2002	PASS 6276329
575	UTG 218	MICHELIN NORTH AMERICA INC.	2003 MICHELIN PILOT XGT H4 3R3VC4YX2002	PASS 6276330

Note: The tire description usually includes an ID number. The tire ID number changes by production week and it is not a tire serial number. Tire ID numbers that are identical indicate that the tires were manufactured during the same week, not that they are the same tire.

**COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH JANUARY 2004
(CI NUMBER SYSTEM EXAMPLE: "CI-208-031220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2003)**

CI NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
CI-108-010831	Astex USA/HID conversion/Headlamp/Electrical dimensional marking req.	MI
CI-108-031205B	Santeca Electronics/2003 Thunder Beam HID conversion/Replaceable light source and ballasts may not comply with S7.7	MI
CI-108-031205C	McCulloch Motors/2003 McCulloch HID conversion/Replaceable light source and ballasts may not comply with S7.7	MI
CI-218-030708	Wombat Trading Co./2003 M2R Motorcycle helmet/Impact at ambient	CT
CI-218-030303	HJC/2002 Z1RZFR-1/Penetration at ambient at high temperature	CT
CI-218-030805	Strategic Sports BVI Ltd./2003 Zamp-S1/Penetration at ambient at low temperature	CT
CI-218-030909	Shokan International Co., Ltd./2003 AFX FX-9/ Impact at ambient	CT

CIs OPENED SINCE LAST REPORT

CI NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
CI-108-040101A	JF Manufacturing/Eagle Eye HID Conversion/Replaceable light sources and ballasts may not comply with S7.7	MI
CI-108-040101B	Streetglow Inc./HID Conversion/Replaceable light sources and ballasts may not comply with S7.7	MI
CI-108-040101C	Outback Products/HID Conversion/Replaceable light sources and ballasts may not comply with S7.7	MI
CI-108-040101D	GR Motorsport Inc./HID Conversion/Replaceable light sources and ballasts may not comply with S7.7	MI
CI-108-040101E	NU Performance Distributing/HID Conversion/Replaceable light sources and ballasts may not comply with S7.7	MI
CI-108-040101F	Global Premier LLC/HID Conversion/Replaceable light sources and ballasts may not comply with S7.7	MI

CIs CLOSED SINCE LAST REPORT

CI NO.	MFR/MY/MAKE/MODEL/FAILURE
CI-108-031205A	Lighting Research/2003 Luks HID conversion/Replaceable light source and ballasts may not comply with S7.7/Manufacturer noncompliance report on 1/21/2004
CI-108-031205D	SPW Industries/2003 HID conversion/Replaceable light source and ballasts may not comply with S7.7/Manufacturer noncompliance report on 1/21/2004
CI-108-031205E	Pacific Micro-Lite/2003 HID conversion/Replaceable light source and ballasts may not comply with S7.7/manufacturer noncompliance report on 1/30/2004
CI-108-030717B	G-Garage/2003 Mcculloch HID conv./Light sources may not comply with dimensional and electrical requirements/Closed by NHTSA 12/8/2003

CAUSE:

CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Manufacturer Inquiry
MD Manufacturer Defect

PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH JANUARY 2004
(PE NUMBER SYSTEM EXAMPLE: "PE-208-031220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2003)

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-108-030602	United Marine Inc./2003 Trailer lamp assembly/Complaint relative to photometry	MI
PE-120-021227	Blue Bird Body Co./2002 School Bus/Tire inflation pressure	CT
PE-121-021104	White's/Keene Manufacturing/2002 Trailer/Updated from OA/Function at ABS device	MI
PE-123-010730	Currie Technologies, Inc./1999 Currie/Electric Bicycle/No engine stop or hand throttle control	CP
PE-208-030501	Toyota/2003 Toyota Tacoma/Sled test-neck compression > 4000	IN
PE-213-030812	Evenflo Co/2003 Evenflo Vanguard/Head excursion measured 32.5 in; req 32 in.	CT
PE-217-030801	Atwood Mobile Products/Emergency exit window/Push out window/Window retention	MI
PE-217-030819	Liberty Bus Inc./2003 Liberty Freedom/School bus/Positive door opening device < 90 degrees	CT
PE-221-030828	Amtran Corp./2003 Amtran IC3S5/Joint tensil strength less than 60%	CT
PE-222-030815	Liberty Bus Inc./2003 Liberty Freedom/Schoolbus/Passenger seat pulled out of floor	CT
PE-225-031202	Starcraft Automotive Group/2003 Starcraft Bus under 10K GVWR/Not enough tether anchorages	CT
PE-301S-030513	US Bus Corp./2003 US Bus/GM chassis sturdibus/Upgraded from OA, insufficient certification data	MI
PE-304-030905	Structural Composites Ind./2003 StructuralComposites/CNG fuel container ruptured during bonfire test	CT
PE-575-031021	Hankook Tire/2003 Hankook mileage plus GT/Traction rating	CT
PE-575-030623	Goodyear Tire & Rubber Co./2002 Goodyear Aquatred 3/Traction rating	CT
PE-VAR-031120	Legendary Motorcars and Coachworks/2003 Lincoln Navigator/Various test failures (108, 111, 120, 205 and 217)	IN

PEs OPENED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-116-040115	Star Brite Inc./2004 Star Brite/Hvy duty brake fluid/High temperature stability	CT
PE-218-030610	Davida UK Limited/2003 Davida motorcycle helmet/Labeling	CT
PE-218-030709	Hong Jin Crown Corp./2002 Icon Alliance/Retention system at ambient	CT
PE-221-030827	Mid Bus Inc./2003 Mid Bus/Joint tensil strength less than 60%	CT
PE-222-030609	Mid Bus Inc./2003 Mid bus/Seat back height and surface area	CT

PEs CLOSED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE
PE-218-030709	Hong Jin Crown Corp./2002 Icon Alliance/Retention system at ambient/Closed by NHTSA 1/30/2004
PE-221-030826	Liberty Bus Inc./2003 Liberty Freedom/School bus/Joint tensil strength less than 60%/Closed by NHTSA 1/16/2004
PE-221-030827	Mid Bus Inc./2003 Mid Bus/Joint tensil strength less than 60%/ Manufacturer noncompliance report on 12/28/2003
PE-222-030609	Mid Bus Inc./2003 Mid bus/Seat back height and surface area/Manufacturer noncompliance report on 12/31/2003

CAUSE:

CT Compliance Test

IN Inspection

CP Complaint

ID Part 574

MI Manufacturer Inquiry

MD Manufacturer Defect